Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	774	compressor and overload and (LED INDICATOR ALARM)	US-PGPUB; USPAT	OR	ON	2005/12/28 12:45
L2	151	compressor and overload same (LED INDICATOR ALARM)	US-PGPUB; USPAT	OR	ON	2005/12/28 11:20
L3	7	("4319298" | "4470092" | "4717985" | "4722019" | "4788647" | "4835706" | "4939437").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 11:53
L4	1	("5975854").PN.	US-PGPUB; USPAT	OR	OFF	2005/12/28 11:53
L5	24	("3735377" | "3763397" | "3783681" | "4060716" | "4102394" | "4372119" | "4390321" | "4390922" | "4399548" | "4425010" | "4429578" | "4479389" | "4884412" | "4909076" | "4913625" | "5056036" | "5109700" | "5203178" | "5224835" | "5362206" | "5509786" | "5602757" | "5610339" | "5707210").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 11:53
L6	24	("4383605" | "4456435" | "4496296" | "4505651" | "4514150" | "4560330" | "4586653" | "4596520" | "4596521" | "4669962" | "4714415" | "4744733" | "4820130" | "4828462" | "4840545" | "4846633" | "4995553" | "5090880" | "5141407" | "5156539" | "5186613" | "5248244" | "5290154" | "5368446").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 11:53
L7	19	("5707210").URPN.	USPAT	OR	ON	2005/12/28 11:55
L8	15	("4667480" | "4735058" | "4876859" | "4913625" | "5463874" | "5707210" | "5875637" | "5941689" | "6047556" | "6099259" | "6206652" | "6302654" | "6393850" | "6450771" | "6619062").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 11:56
L9	4	("4989414" | "6058729" | "6202438" | "6213731").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 11:57
L10	27	("3735377" | "3783681" | "4060716" | "4102394" | "4372119" | "4390321" | "4390922" | "4399548" | "4425010" | "4429578" | "4479389" | "4884412" | "4909076" | "4913625" | "5056036" | "5109700" | "5203178" | "5224835" | "5362206" | "5381692" | "5509786" | "5602757" | "5610339" | "5707210" | "5975854" | "5984645" | "6125642").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 11:59
L11	28	("1987725" | "2279214" | "2313969" | "2324161" | "2338515" | "2369986" | "2771528" | "2909719" | "3023350" | "3200274" | "4092573" | "4376296" | "4748531" | "4791329" | "5021915" | "5023744" | "5118260" | "5200872").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 12:01
L12	30	("2682005" | "3155877" | "3474372" | "3544869" | "3586910" | "3636426" | "3695054" | "3718879" | "3852648" | "3898527" | "3913342" | "3921117" | "3959984" | "3965392" | "4086558" | "4224591" | "4376926" | "4450496" | "4518324" | "4563624" | "4716486" | "4761592" | "4928503" | "4955795" | "5055726" | "Re31367").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 12:09
L13	23	("5200872").URPN.	USPAT	OR	ON	2005/12/28 12:12
L14	37357	(stator motor) same (LED INDICATOR ALARM)	US-PGPUB; USPAT	OR	ON	2005/12/28 12:46
L15	120020	(stator motor) same (LED INDICATOR ALARM)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:19
L16	1425	15 and compressor and (overload overtemperature overcurrent overvoltage thermal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 13:21

L17	710	16 and (house housing)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 12:47
L18	32	("2875382" | "3660718" | "3742303" | "3786311" | "3846675" | "3955121" | "4000446" | "4004201" | "4060844" | "4068283" | "4084406" | "4252394" | "4297741" | "4347541" | "4404612" | "4547715" | "4689712" | "4733321" | "4796148" | "4814935" | "4825330" | "4914541" | "4939909" | "4943888" | "5056032" | "5199898" | "5303560" | "5336105" | "5369542" | "5943204" | "6097107").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 12:53
L19	28	("1987725" | "2279214" | "2313969" | "2324161" | "2338515" | "2369986" | "2771528" | "2909719" | "3023350" | "3200274" | "4092573" | "4376296" | "4748531" | "4791329" | "5021915" | "5023744" | "5118260" | "5200872").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 13:02
L20	9	("2986685" | "3569753" | "3753069" | "3777240" | "4078192" | "4219071" | "4259845" | "4384312").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 13:10
L21	6	("2986685").URPN.	USPAT	OR	ON	2005/12/28 13:11
L22	4	("2400665" | "4265091" | "Re31367").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/12/28 13:12
L23	2	("4547825").URPN.	USPAT	OR	ON	2005/12/28 13:13
L24	55	15 and scroll near2 compressor and (overload overtemperature overcurrent overvoltage thermal)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:17
L25	38625	scroll near2 compressor motor near3 protect$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:18
L26	4805	25 and (LED alarm indicator indication)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 13:26
L27	2198	26 and (house housing)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 13:26
L28	1101	25 same (LED alarm indicator indication)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 13:26
L29	386	28 and (house housing)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:16
L30	1114	(361/22,23,24,26,30).CCLS.	US-PGPUB; USPAT	OR	OFF	2005/12/28 14:22

L31	0	("25and30").PN.	US-PGPUB; USPAT	OR	OFF	2005/12/28 14:17
L32	408	30 and 25	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:18
L33	192	scroll near2 compressor and motor near3 protect$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:03
L34	1709	compressor and motor near3 protect$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:18
L35	125	30 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:22
L36	28	35 and (LED INDICATOR ALARM)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:19
L37	1003	(417/12,18,32).CCLS.	US-PGPUB; USPAT	OR	OFF	2005/12/28 14:22
L38	41	37 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:44
L39	11	"5690475"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:44
L40	54	scroll near2 compressor same (overload thermal near2 protect$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:55
L41	146	scroll near2 compressor and (overload thermal near2 protect$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:59
L42	6	41 and motor near4 (alarm indicator)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:10

L43	8	41 and motor same (alarm indicator)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 14:57
L44	46	scroll near2 compressor and thermal near2 protect$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:00
L45	13	scroll near2 compressor and fault near3 (indication indicator LED alarm)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:02
L46	469	compressor and fault near3 (indication indicator LED alarm)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:11
L47	44	46 and motor near3 protect$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:03
L48	2712	winding near4 (alarm indicator)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:10
L49	27	compressor and 48	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/28 15:11